Date - 9/1/25

	Date - 9/1/25				
Baneberry	Walkway Repair	Step Repair	Comments	Priority	
301	OK	OK			
302	Repair	OK	Several areas roots pushing up bricks	1	
303	OK	OK			
304	OK	OK			
305	OK	OK			
306	Repair	Repair	Repaired 2025		
307	OK	Repair	Mortar missing at steps	2	
308	OK	OK			
309	Repair	OK	Bricks pushed up by roots - Bad	1	
310	OK	OK			
311	OK	OK			
312	OK	OK			
313	OK	OK			
314	OK	OK			
315	OK	OK			
316	OK	OK	Walkway ok but berm needs to be removed	2	
317	OK	OK			
318	OK	OK			
319	OK	OK			
320	Repair	OK	Bricks pushed up by roots	1	
Sycamore	Walkway Repair	Step Repair	Comments	Priority	
321	Repair	OK	Bricks need leveling, several broken	2	
322	Repair	OK	Bricks need leveling, several broken	2	
323	Repair	OK	3 uneven, trip hazard, need leveling	2	
324	Repair	OK	Bricks need leveling, several broken	2	
325	Repair	OK	3 uneven, trip hazard, need leveling	2	
326	Repair	OK	Several need leveling	2	
327	Repair	OK	Several need leveling	2	
328	Repair	OK	Several need leveling	2	
329	Repair	OK	Several need leveling	2	
Whisperwood	Walkway Repair	Step Repair	Comments	Priority	
Mail Kiosk	Repair	OK	Several need Leveling	2	
330	Repair	OK	Sunken area near Magnolia tree	2	
331	Repair	OK	1 brick in middle needs leveling	2	
332	Repair	OK	Several need Leveling	2	
333	Repair	OK	Uneven near stepping stone	2	
334	OK	OK			
335	Repair	OK	Brick under tree between 334 &335	2	
336	OK	OK			
337	Repair	OK	Sunken area near drain and garage	2	

			L	
338	Repair	OK	Leveling, close large gaps, broken bricks	2
339	Repair	OK	Leveling near proch and at timbers	2
340	Repair	OK	Broken bricks near garage & garage wind	2
341	Repair	OK	Several need leveling and replacing	2
342	Repair	OK	Several at top of hill & two in walkway	2
343	Repair	OK	Several need Leveling - Bad	1
Weymouth	Walkway Repair	Step Repair	Comments	Priority
344	Repair	OK	2 Sunken areas under tree	2
345	OK	OK	Repaired in 2025	
346	OK	OK		
347	OK	OK		
348	OK	OK		
349	Repair	OK	Replace broken brick near parking sign	2
350	OK	OK		
351	OK	OK		
352	OK	OK		
353	Repair	OK	One sunken near crepe myrtle	2
354	OK	OK		
355	OK	OK	Repaired 2025	
356	OK	OK		
Linden	Walkway Repair	Step Repair	Comments	Priority
357	OK	OK		
358	Repair	OK	Sunken bricks	2
359	Repair	OK	Bricks up near steps, tree roots	1
360	OK	OK	Work Order approved to add drain	
361	OK	OK	• •	
362	Repair	OK	Cracked brick popped up	2
363	Repair	OK	Bricks near steps sunken	2
364	OK	OK	•	
365	Repair	OK	Repaired 2025	
366	OK	OK		
367	Repair	OK	Repaired 2025 - Bricks at garage need rep	2
368	Repair	OK	Roots pushing up bricks	1
369	Repair	OK	Roots pushing up bricks	2
370	Repair	OK	Roots pushing up bricks	2
	Donain	OV	Roots pushing up bricks	2
371	Repair	OK	Roots pushing up offers	_
371 372	_	OK OK	1 0 1	2
372	Repair	OK	Several bricks up and some sunken Comments	2
372 Wintercrest W	Repair Walkway Repair	OK Step Repair	Several bricks up and some sunken	
372	Repair Walkway Repair OK	OK	Several bricks up and some sunken Comments	2
372 Vintercrest W 373 374	Repair Walkway Repair OK Repair	OK Step Repair OK OK	Several bricks up and some sunken	2 Priority
372 Vintercrest W 373 374 375	Repair Walkway Repair OK Repair OK	OK Step Repair OK OK OK	Several bricks up and some sunken Comments	2 Priority
372 Vintercrest W 373 374 375 376	Repair Walkway Repair OK Repair OK OK OK	OK Step Repair OK OK OK OK OK	Several bricks up and some sunken Comments	2 Priority
372 Wintercrest W 373 374 375	Repair Walkway Repair OK Repair OK	OK Step Repair OK OK OK	Several bricks up and some sunken Comments	2 Priority

380	OK	OK		
381	OK	OK		
Lyndfield	Walkway Repair	Step Repair	Comments	Priority
382	OK	OK		
383	Repair	OK	Bricks uneven at end of walkway	2
384	OK	OK	Director director di cita di Wantiway	
385	OK	OK		
386	Repair	OK	Missing brick next to step	2
387	OK	OK	Tribbing offer next to step	_
388	OK	OK		
389	OK	OK		
390	OK	OK		
391	Repair	OK	Repaired 2025	
392	OK	OK		
393	OK	OK		
394	OK	OK		
395	Repair	OK	Uneven bricks near steps	2
396	Repair	OK	Uneven bricks near bird feeder	2
397	OK	ok		
398	OK	OK		
399	OK	OK		
400	OK	Repair	Missing mortar	
401	OK	Repair	Uneven bricks - Work Order Issued	1
Brampton	Walkway Repair	Step Repair	Comments	Priority
402	Repair	OK	Uneven brick at steps	2
403	OK	OK		
404	OK	OK		
405	OK	OK		
406	OK	OK		
407	OK	Repair	top row of bricks need pointing up	2
408	OK	OK		
409	Repair	OK	Water pooling - need to repalce drain pipe	1
410	OK	OK		
411	OK	OK		
412	OK	OK		
413	OK	OK		
414	OK	OK		
Vintercrest East	Walkway Repair	Step Repair	Comments	Priority
415	OK	OK		
416	Repair	OK	Uneven bricks at end of walkway	2
	OV	OK		
417	OK	OK		
417	OK OK	OK		
418	OK	OK		

422	Repair	OK	Water pooling	2
423	OK	OK		
424	Repair	OK	Water pooling - need to repalce drain	1
425	Repair	OK	Uneven bricks	2
426	OK	Repair	Need repointing at steps	2
427	Repair	OK	Uneven bricks some missing bricks	2
428	Repair	OK	Uneven bricks at garage	1
429	Repair	OK	Uneven bricks	2
430	OK	OK		
431	OK	OK		
432	Repair	OK	Uneven bricks at several places	2
433	OK	OK		
434	OK	OK	Repaired 2025	
435	OK	OK		
436	OK	OK		
Crossvine	Walkway Repair	Step Repair	Comments	Priority
437	OK	OK		
438	Repair	OK	Repaired 2025	
439	OK	OK		
440	OK	OK		
441	OK	OK		
442	OK	OK		
443	OK	OK		
444	Repair	OK	Bricks sunk	2
445	OK	OK	Bricks sunk	2
446	OK	OK		
447	OK	OK		
448	OK	OK		
449	Repair	OK	Repaired 2025	
450	OK			
451	OK	OK		
452	OK OK	OK OK		
434				
453	OK	OK		
	OK OK	OK OK	Comments	Priority
453	OK OK OK	OK OK OK	Comments Gap in top step need filling	Priority 2
453 Lower Beech	OK OK OK Walkway Repair	OK OK OK Step Repair		
453 Lower Beech 455	OK OK OK Walkway Repair Repair	OK OK OK Step Repair Repair	Gap in top step need filling	2
453 Lower Beech 455 456	OK OK OK Walkway Repair Repair Repair	OK OK OK Step Repair Repair OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks	2 2
453 Lower Beech 455 456 457	OK OK OK Walkway Repair Repair Repair Repair	OK OK OK Step Repair Repair OK OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks	2 2
453 Lower Beech 455 456 457 458	OK OK OK Walkway Repair Repair Repair Repair OK	OK OK OK Step Repair Repair OK OK OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks	2 2
453 Lower Beech 455 456 457 458 459	OK OK OK Walkway Repair Repair Repair Repair OK OK	OK OK OK Step Repair Repair OK OK OK OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks	2 2
453 Lower Beech 455 456 457 458 459 460	OK OK OK Walkway Repair Repair Repair Repair OK OK OK	OK OK OK Step Repair Repair OK OK OK OK OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks Walkway to 455 - 457 unlevel bricks	2 2 2
453 Lower Beech 455 456 457 458 459 460 461	OK OK OK Walkway Repair Repair Repair OK OK OK OK	OK OK OK Step Repair Repair OK OK OK OK OK OK OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks Walkway to 455 - 457 unlevel bricks	2 2 2
453 Lower Beech 455 456 457 458 459 460 461 462	OK OK OK OK Walkway Repair Repair Repair OK OK OK OK	OK OK OK OK Step Repair Repair OK OK OK OK OK OK OK OK	Gap in top step need filling Walkway to 455 - 457 unlevel bricks Walkway to 455 - 457 unlevel bricks Broken bricks need replacing	2 2 2

466	Repair	Repair	Voles pushing bricks up	2
467	Repair	OK	Voles pushing bricks up	2
468	Repair	OK	Voles pushing bricks up	2
469	OK	OK		
470	OK	Repair	Gap in top step need filling	2
471	OK	OK		
472	OK	OK		
473	OK	Repair	Gap in top step need filling	2
474	OK	OK		
475	OK	OK		
476	OK	OK		
477	OK	OK		
478	Repair	OK	Bricks up	2
479	OK	OK	-	
480	Repair	OK	Water pooling at end of walkway	2
481	OK	OK		
482	OK	OK		
483	OK	OK		
484	Repair	Repair	Gap in top and bottom steps need filling	2
Upper Beechma	Walkway Repair	Step Repair	Comments	Priority
485	Repair	OK	Voles pushing bricks up	2
486	OK	OK		
487	OK	OK		
487 489		OK OK		
	OK			
489	OK OK	OK	Repaired 2025	
489 490	OK OK OK	OK OK	Repaired 2025	
489 490 491	OK OK OK OK	OK OK Repair	Repaired 2025 Needs filling in	2
489 490 491 492	OK OK OK OK	OK OK Repair OK		2
489 490 491 492 493	OK OK OK OK OK OK Repair	OK OK Repair OK OK		2 2
489 490 491 492 493 494	OK OK OK OK OK OK OK OK Repair	OK OK Repair OK OK OK	Needs filling in	
489 490 491 492 493 494 495	OK OK OK OK OK OK OK Repair OK Repair	OK OK Repair OK OK OK OK	Needs filling in Voles pushing bricks up	2
489 490 491 492 493 494 495 496	OK OK OK OK OK OK OK Repair OK Repair Repair	OK OK Repair OK OK OK OK OK OK	Needs filling in Voles pushing bricks up Bricks at steps	2 2
489 490 491 492 493 494 495 496 497	OK OK OK OK OK OK OK OK Repair OK Repair Repair	OK OK Repair OK OK OK OK OK OK OK OK Repair	Needs filling in Voles pushing bricks up Bricks at steps	2 2
489 490 491 492 493 494 495 496 497 498	OK OK OK OK OK OK OK Repair OK Repair Repair Repair OK	OK OK Repair OK	Needs filling in Voles pushing bricks up Bricks at steps Roots pushing bricks up,	2 2 1
489 490 491 492 493 494 495 496 497 498 499	OK OK OK OK OK OK OK Repair OK Repair Repair Repair OK OK	OK OK Repair OK OK OK OK OK OK OK OK OK CK OK OK Repair	Needs filling in Voles pushing bricks up Bricks at steps Roots pushing bricks up,	2 2 1
489 490 491 492 493 494 495 496 497 498 499 500	OK OK OK OK OK OK OK Repair OK Repair Repair Rok OK OK	OK OK Repair OK OK OK OK OK OK OK OK OK Repair OK	Needs filling in Voles pushing bricks up Bricks at steps Roots pushing bricks up,	2 2 1
489 490 491 492 493 494 495 496 497 498 499 500 501	OK OK OK OK OK OK OK Repair OK Repair Repair RoK OK OK OK	OK OK OK Repair OK	Needs filling in Voles pushing bricks up Bricks at steps Roots pushing bricks up,	2 2 1
489 490 491 492 493 494 495 496 497 498 499 500 501 502	OK OK OK OK OK OK OK Repair OK Repair Repair Repair OK OK OK	OK OK Repair OK Repair OK Repair OK OK OK	Needs filling in Voles pushing bricks up Bricks at steps Roots pushing bricks up, Need repointing at steps	2 2 1